

*unmailed 12-26-23*  
 BOS  
 Joe Black  
 Chris

**Municipal Waste Landfill Inspection Report**



Permit Number	100022
Facility Name	CHRIN BROS SANI LDFL
Address	1225 INDUSTRIAL DR
City/State/Zip	EASTON PA 18042-6829
Municipality	Williams Township
Responsible Official	Gregory Chrin
Person Interviewed	Joseph Klobusicky
Lead Inspector	AMY E FAULCH
Site ID	238053
PF ID	240650
Inspection Start Date	12/13/2023 08:26 AM
Inspection Type	RTNC - Routine/Complete Inspection
Permit Expiration Date	01/06/2030

EPA ID Number	
Operator Name	CHRIN BROS INC
Address	1225 INDUSTRIAL DR
City/State/Zip	EASTON PA 18042-6829
County	Northampton
Title	Owner/ Operator
Title	Environmental Manager
Telephone #	1
Title	SLD WSTE SUPV
Client ID	42952
SF ID	201820
Inspection End Date	12/13/2023 10:30 AM
Inspection Result	No Violations Noted
Days/Week Operated	6
Max. Daily Volume	2000 Tons/Day

**Check Lists**

Municipal Waste Landfill (0131)			
Status	Requirement	Chapter Citation	Line Item
<b>GENERAL PROVISIONS</b>			
No Violation	Required insurance in effect	271.371	1
	(expiration date) 12/01/2024		1A
No Violation	Operation in accordance with approved plans and permit.	273.201(c)(2)	2
No Violation	Operation within permit boundaries (vertical and horizontal).	273.201(c)(2)	3
No Violation	Disposal Timing and sequence as per Section 273.112(1).	273.201(c)(2)	4
Violation	No unapproved wastes or liquids.	273.201(d)-(m)	5

No Violation	Isolation distances are adhered to.	273.202(a)	6
No Violation	Facilities certification requirements followed.	273.203(a), (b)	7
No Violation	Written Department approval of new construction prior to waste disposal.	273.203(c)	8
<b>DAILY OPERATIONS</b>			
No Violation	Proper signs posted.	273.211(a)	9
No Violation	Site perimeter clearly marked and grid coordinate system in use.	273.211(b)-(d)	10
No Violation	Proper barriers installed around site and access controlled when attendant not present.	273.212(a)-(i)	11
No Violation	Access roads maintained and negotiable by collection vehicles.	273.213(a)-(i)	12
No Violation	Approved means of measuring and inspected waste utilized. Remark: Chrin's scale was last calibrated on 10/19/23. Chrin recorded 60 overweight vehicles in November 2023.	273.214(a), (b)	13
No Violation	Adequate equipment on-site and stand-by equipment available.	273.215(a), (b)	14
No Violation	Vehicles directed promptly to unloading area and promptly unloaded.	273.216(a), (b)	15
No Violation	Solid waste spread and compacted as approved by Department as part of permit.	273.216(c)	16
No Violation	Operator implements fugitive air contaminant control/measures and prevents and controls air pollution including no exceeding of ambient air quality standards, no open burning, and minimizing generation of fugitive dust emissions from facility.	273.217(a)	17
No Violation	Operator complies with Air Quality Plan approval and Air quality Operating Permit.	273.217(b)	18
No Violation	Operator does not cause or allow attraction, harborage, or breeding of vector.	273.218(a)	19
No Violation	Operator implements nuisance minimization and control plan.	273.218(b)(1)	20

No Violation	Operator performs regular, frequent, and comprehensive site inspections to reduce potential for offsite odors.	273.218(b)(2)	21
No Violation	Operator promptly addresses and correct problems and deficiencies discovered during inspections.	273.218(b)(3)	22
No Violation	Operator implements nuisance minimization and control plan to minimize and control other conditions harmful to the environment or public health, or which create safety hazards, odors, dirt, noise, unsightliness and other public nuisances. Remark: Chrin's daily odor patrol logs and nuisance load logs were reviewed. Chrin is conducting daily odor patrols in accordance with their nuisance minimization and control plan.	273.218(c)	23
No Violation	Operator does not receive solid waste at a landfill in excess of the maximum or average daily volume approved in the permit. Remark: Daily tonnages were reviewed since the last inspection. There were no exceedances of the 2,000 ton daily limit. The greatest tonnage to date in December 2023 was 615 tons.	273.221(a)	24
No Violation	Operator implements radiation protection action plan.	273.223(a)	25
No Violation	Operator monitors incoming waste in accordance with Department's guidance or in a manner at least as protective of the environment, facility staff and public health and safety. Remark: Radiation source checks were reviewed. Chrin has had no radiation hits since the last inspection.	273.223(b)	26
No Violation	Radiation detector elements shall be as close as practical to wasteload and in appropriate geometry to monitor the waste.	273.223(c)	27
No Violation	Operator has portable radiation monitors capable of determining the dose rate and presence of contamination of a vehicle that has caused an alarm. Upon exceedance of alarm level, a radiological survey of the vehicle is performed.	273.223(d)	28
No Violation	Operator notifies Department immediately and isolates vehicle when radiation dose rates are exceeded.	273.223(e)	29

No Violation	Monitoring equipment is calibrated at frequency specified by manufacturer, but not less than once a year.	273.223(f)	30
No Violation	If radioactive material is detected, vehicle containing material shall not leave facility without written Department approval and an authorized federal Department of Transportation exemption form.	273.223(g)	31
No Violation	Uniform cover of the approved daily cover material is placed on exposed solid waste at the end of each working day or at the end of every 24 hours, whichever interval is less.	273.232(a)	32
No Violation	If intermediate cover requires revegetation, it is established within 30 days.	273.233(e)	33
No Violation	Slopes constructed during daily landfilling and intermediate cover activities may not exceed 50 percent.	273.233(f)	34
No Violation	Operator does not cause or allow waste pollution within or outside the site from operation of the facility.	273.241(a)-(c)	35
Applicable	Operator has restored or replaced adversely affected water supply with an alternative source of like quantity and quality.	273.245(a)	36
Not Applicable	Temporary water supply is provided within 48 hours.	273.245(b)	37
Not Applicable	Permanent water supply is provided within 90 days.	273.245(c)	38
No Violation	No waste 15 feet of inside top of the lined perimeter berm.	273.252(e)	39
No Violation	Lined perimeter berm 4 ft. high constructed and maintained along edge of the lined disposal area.	273.252(f)	40
No Violation	Edge of liner clearly marked.	273.252(g)	41
Not Applicable	Alternate leachate recirculation method may be used if approved if one of the liner systems is a composite liner.	273.274(b)	42
No Violation	Underground pipes used to transport leachate to leachate storage impoundments or tanks equipped with secondary containment or comply with 245.445.	273.275(g)	43

Not Applicable	Operator isolates coal seams, coal outcrops and coal refuse from waste deposits to prevent combustion of waste and damage to liner.	273.291(a)	44
Not Applicable	Mine openings within site sealed as approved by Department.	273.291(b)	45
Not Applicable	Operator implements plan for controlling potential damage from subsidence submitted and approved under 273.120.	273.291(c)	46
No Violation	Landfill designed, constructed, maintained and operated to prevent and minimize potential for fire, explosion, or release of solid waste constituents into air, water, or soil of the Commonwealth.	273.301	47
No Violation	Emergency equipment including portable fire extinguishers, fire control equipment, spill control equipment, and decontamination equipment available. For fire equipment requiring water, facility has a water supply of or adequate quantity and pressure to supply the equipment.	273.302(a)	48
Violation	Emergency equipment tested and maintained.	273.302(c)	49
No Violation	Adequate space maintained to allow unobstructed movement of emergency personnel and equipment.	273.302(d)	50
No Violation	Litter controlled/collected and barriers/fences in place.	273.220(a)-(c)	51
<b>COVER/SLOPES/REVEGETATION</b>			
No Violation	Daily/intermediate cover meets performance and design requirements. Remark: Flagging was observed in the 3E waste relocation area west of the working face. Additional cover is needed in this area. Chrin is reminded to apply cover in accordance with 25 Pa. Code 273.232 and 273.233 to the 3E waste relocation area at the end of each day after waste removal activities.	273.232(b), 273.233(b), (c)	52
No Violation	Minimum 5 day supply of daily and intermediate cover maintained on-site.	273.232(c) & 273.233(d)	53
No Violation	Intermediate cover applied within time limits.	273.233(a)	54
Violation	Intermediate slopes do not exceed 50%.	273.232(d)	55

No Violation	Cap placed over entire surface of final lift meets performance standards.	273.234(a)(1)	56
No Violation	Final cover meets performance and design requirements; applied within time limits.	273.234(b)-(e)	57
No Violation	Final slopes stable and erosion controlled.	273.234(f)	58
No Violation	Final slopes graded 3-15% or terraced to 33% as approved.	273.234(g)	59
No Violation	Minimum revegetation and successful revegetation requirements adhered to.	273.235(a)-(e) & 273.236(a), (b)	60
<b>WATER QUALITY PROTECTION</b>			
No Violation	Surface and groundwater treatment facilities properly operated and maintained.	273.241(b)	61
No Violation	Surface water percolation minimized/prevented.	273.242(b)(1) & 273.234(e)(4)	62
No Violation	Soil erosion and sedimentation controls designed and implemented as per approved plans; gullies over nine inches repaired.	273.242(a)-(c)	63
No Violation	Sedimentation ponds and discharge structures designed, constructed, operated, and maintained in accordance with Chapters 273, 102, and 105.	273.243(a)-(g) & 273.244	64
<b>LINER SYSTEM</b>			
No Violation	Liner system designed, constructed, operated, and maintained when required.	273.251(a), (b)	65
No Violation	Edge of liner requirements adhered to (i.e., no waste within 25 feet of adjacent liner, 4 feet high lined berm, to prevent lateral escape of leachate, adequate spacing on inside of berm to collect stormwater and sediment).	273.252(d)	66
No Violation	Leachate detection zone monitored weekly.	273.255(c)	67
No Violation	Protective cover protects primary liner and leachate collection system and allows free flow of leachate into the collection system.	273.257(a)	68
No Violation	Protective cover meets minimum requirements and at least 18 inches thick.	273.257(b)	69
No Violation	Leachate collection system within protective cover meets minimum requirements.	273.258(a), (b)	70

No Violation	Barrier designed, constructed and maintained as required to prevent lateral migration of leachate off-site in surface mined areas.	273.259(a)-(d)	71
No Violation	8 feet of select waste placed over protective cover.	273.260	73
<b>LEACHATE TREATMENT</b>			
No Violation	Leachate collected and handled through Department approved method(s).	273.272(a)-(c)	74
Not Applicable	Leachate transportation requirements adhered to.	273.273(a)-(c)	75
No Violation	Cessation of site operation if alternate leachate handling not available.	273.273(d)	76
Not Applicable	Leachate treatment system permitted and fully operational at least 3 years before closure.	273.273(e)	77
Not Applicable	Leachate recirculation in accordance with regulations.	273.274(1)-(4)	78
No Violation	Leachate collection and storage systems on-site have capacity of 30 days or 250,000 gallons, whichever is greater.	273.275(a)-(f)	79
No Violation	Leachate flow rate measured daily; analyzed quarterly.	273.276(a)-(b)	80
No Violation	Department notified when remedial action(s) required.	273.277(1)-(4)	81
<b>WATER QUALITY MONITORING</b>			
No Violation	Approved monitoring system installed and maintained.	273.281(a), (b) & 273.283	82
No Violation	Quarterly and annual monitoring requirements adhered to and results submitted Department within time constraints.	273.284 & 273.285	83
No Violation	Groundwater assessment plan submitted and implement as required.	273.286(a)-(g)	84
No Violation	Groundwater abatement plan submitted and implemented as required.	273.287(a)-(f)	85
<b>RECORDKEEPING AND REPORTING</b>			
No Violation	Operational records maintained, available and submitted as required.	273.288 & 273.311-273.313	86

No Violation	Daily Operational Records kept in accordance with regulations for the life of the facility bond or longer if necessary.	273.311(d)	87
No Violation	Operator submits quarterly operation report.	273.312	88
No Violation	Operator submits annual operation report with fee.	273.313	89
<b>MINERALS AND GAS</b>			
No Violation	Gas venting and monitoring in accordance with approved plans.	273.292(a)-(d)	90
No Violation	Combustible gas levels not exceeded.	273.292(e)	91
No Violation	Forced gas venting if required.	273.292(f)	92
No Violation	Gas recovery conducted as per approved plan and §273.293, including annual analysis.	273.293(a), (b)	93
<b>EMERGENCY PROCEDURES</b>			
No Violation	Contingency plan implemented if there is an emergency.	273.303(a)-(c)	94
<b>RECYCLING</b>			
No Violation	Operator shall salvage and recycle waste in accord with recycling plan. (273.196)	273.331(a)	95
No Violation	Salvaging and recycling controlled by operator and prevents interference within operations and prevents health hazardous nuisance.	273.331(b)	96
No Violation	Salvaged materials stored in an approved area or transported offsite.	273.331(c)	97
No Violation	Drop off center established for at least three recyclables.	273.332(a)	98
No Violation	Drop off center properly located, contains bins or containers, open at least 8 hours per week and 4 hours during evenings or weekends.	273.332(b), (c)	99
No Violation	Approved public notice of availability of drop off center availability is provided.	273.332(d)	100
No Violation	On or before January 15 each year, operator informs municipality in writing of weight and type of materials recycled previous year.	273.332(e)	101



**SPECIAL HANDLING AND RESIDUAL WASTES**

No Violation	Special handling and residual wastes disposed with prior Department approval, and in accordance with permit and Chapter 273.	273.501	102
Not Applicable	Infectious waste disposal restrictions adhered to.	273.511(a)-(d)	103
Not Applicable	Chemotherapeutic waste disposal restrictions adhered to.	273.512	104
No Violation	Sewage sludge co-disposal and monofill requirements followed.	273.513	105
No Violation	Sewage sludge sampling requirements adhered to and sludge meets standards for control of pathogens, vectors, and odors.	273.513(c)	106
Not Applicable	Disposal of municipal waste incineration ash in landfill or landfill cell that meets Chapter 273 requirements.	273.514(a)	107
Not Applicable	Ash residue disposal in dedicated landfill or landfill cell unless co-disposal in accordance with Chapter 273 (including leachability treatment).	273.514(b)	108
Not Applicable	Ash residue covered immediately or as approved by the Department.	273.514(c)	109

**BONDING AND INSURANCE**

No Violation	Bond filed with Department.	271.312	110
No Violation	Bond maintained in an amount and with guarantees as required.	271.333(b)	111
	Bond amount \$		111A
	Phased deposit due date		111B
No Violation	Proof of a commercial policy of liability insurances submitted to the Department as specified by 271.374.	271.374	112
	Policy # GEC003617612		112A
	Insurer (company name) Greenwich Insurance Company		112B
	Expiration Date: 12/01/2024		112C

**Comments**

On December 13, 2023, the PA Department of Environmental Protection ("Department") conducted a routine complete inspection at Chrin Bros. Sanitary Landfill ("Chrin"). Representing the Department was Amy Faulch ("this inspector"). Joseph Klobusicky provided a site tour and was interviewed on behalf of Chrin. See the 12/13/23 odor patrol log for weather details.

The following Department personnel entered the landfill since the last inspection on 11/16/23: A. Faulch, R. Mullin and M. Caccese on 11/16/23; M. Glogowski on 11/24/23; and A. Faulch on 12/13/23.

#### SITE TOUR:

Prior to entering Chrin, this inspector conducted an odor patrol in the areas surrounding the facility. A light, intermittent gas odor was detected along I-78 adjacent to the landfill and at the intersection of Morgan Hill Rd. and Industrial Dr. A very light "fishy" garbage odor was detected along Cedarville Rd. near the metal recycler. A light, persistent garbage odor was detected along Morgan Hill Rd. at the hairpin turn. A light, intermittent garbage odor was detected at the intersection of Morgan Hill Rd. and Industrial Dr. See the 12/13/23 odor patrol log for details.

During this site tour the working face area was observed in 9B. Two trucks were unloading. Moderate garbage odors were detected in the immediate working face area. A strong gas odor was detected at the access road entrance to the working face area. Perimeter line misters were in operation, and a hose with neutralizer was in use at the working face. Some gas odors were also detected in the area surveyed during the 11/16/23 inspection, although some of the gas wells have been repaired in this area.

Some gas odors were also detected at the top of 3E near the waste relocation area. The 3E waste relocation area where waste was recently removed west of the working face is in need of some additional cover, as significant flagging was observed in this area. Cover is being removed from some of the 3D/3E slopes and relocated waste is being added to this area to bring it to grade before final capping. Mr. Klobusicky stated that some of the gas wells may be off in this area due to this work.

Some gas odors were also detected along the east access road. Leachate repairs were recently completed in this area. A truckwash was set up along the north access road. The 501 building demolition is continuing. Pyrotechnic "screamers" are being used for bird control.

Flare 3 was in operation at the time of this inspection with a temperature of 1761°F and a flow of 1895 scfm. Flare 4 and the stick flare were not in operation. Engines for the gas to energy plant are still being refurbished.

**ODOR COMPLAINTS:**

Since the last inspection report from the 11/16/23 inspection was issued on 12/4/23, the Department received no odor complaints.

---

**Check List Comments**

---

**Line Item 13** - Approved means of measuring and inspected waste utilized.

**Remark:** Chrin's scale was last calibrated on 10/19/23. Chrin recorded 60 overweight vehicles in November 2023.

**Line Item 23** - Operator implements nuisance minimization and control plan to minimize and control other conditions harmful to the environment or public health, or which create safety hazards, odors, dirt, noise, unsightliness and other public nuisances.

**Remark:** Chrin's daily odor patrol logs and nuisance load logs were reviewed. Chrin is conducting daily odor patrols in accordance with their nuisance minimization and control plan.

**Line Item 24** - Operator does not receive solid waste at a landfill in excess of the maximum or average daily volume approved in the permit.

**Remark:** Daily tonnages were reviewed since the last inspection. There were no exceedances of the 2,000 ton daily limit. The greatest tonnage to date in December 2023 was 615 tons.

**Line Item 26** - Operator monitors incoming waste in accordance with Department's guidance or in a manner at least as protective of the environment, facility staff and public health and safety.

**Remark:** Radiation source checks were reviewed. Chrin has had no radiation hits since the last inspection.


**Line Item 52** - Daily/intermediate cover meets performance and design requirements.

**Remark:** Flagging was observed in the 3E waste relocation area west of the working face. Additional cover is needed in this area. Chrin is reminded to apply cover in accordance with 25 Pa. Code 273.232 and 273.233 to the 3E waste relocation area at the end of each day after waste removal activities.

**Inspection Report Signature Page**

This inspection report is notice of the findings of an inspection conducted by a representative of the Department. This report is formal notification of any violations observed during the inspection. Additional notification of violations may be issued concerning either Violations noted herein, or other violations identified as a result of review of laboratory analyses. This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein. Signature by the persons interviewed does not necessarily imply concurrence with the findings of this report, but does acknowledge that the person was shown the report or that a copy was left with the person.

**Signatures**

<b>Person Interviewed</b>	Unable To Obtain Reason: Sent to the facility via email.	<b>Date</b>	--/--/----
<b>Inspector</b>		<b>Date</b>	12/22/2023

Investigator: A. Faulch Date: 12/13/23  
 Weather Conditions: Sunny 31°F wind SW @ 5mph, 79% H.

CASE: Chim Landfill

**ODOR PATROL SURVEY**

SURVEY LOCATION	TIME	ODOR INTENSITY S = Strong M = Moderate SL = Slight N = None	ODOR DURATION P = Persistent I = Intermittent N = None	ODOR DESCRIPTION EG = Rotten Egg LFG = Landfill Gas G = Garbage S = Sewage D = Dredge O = Other (describe)	COMMENTS & OBSERVATIONS
1-78	826	SL	1	LFG	light gas odor adjacent to landfill
MRR Industrial	829	SL	1	LFG	light gas odor
Cedarville	830	SL	1	G	very light "fishy" garbage odor near metal shed
Knoxwood	832	N			
Auburn	833	N			
Sewage Treatment Plant	836	N			
Congress Road	838	N			
Clubhouse	840	N			
Turkey	841	N			
Merton	841	N			
Water Tower	844	N			
Clubhouse	846	N			
Pinehurst	847	N			
Pine Valley	848	N			
Bethpage	850	N			
Waterford	850	N			
Preswick	851	N			
Old Courthouse	851	N			

Investigator: A. Faulch Date: 12/13/23  
 CASE: Chrin Landfill **ODOR PATROL SURVEY**

Weather Conditions: \_\_\_\_\_

SURVEY LOCATION	TIME	ODOR INTENSITY S = Strong M = Moderate SL = Slight N = None	ODOR DURATION P = Persistent I = Intermittent N = None	ODOR DESCRIPTION EG = Rotten Egg LFG = Landfill Gas G = Garbage S = Sewage D = Dredge O = Other (describe)	COMMENTS & OBSERVATIONS
St. Andrew	852	N			
Oak Hill	853	N			
Spring Valley	854	N			
Mt. Top	858	N			
Waltham Loop	859	N			
MHR	900	SL	I	G	light garbage odor @ hairpin turn
MHR x Industrial	901	SL	I	G	light garbage odor
Industrial	902	N			
Morrake	905	N			
MHR	909	N			
Spring Valley	910				
MHR	914	SL	P	G	light garbage odor @ hairpin turn
MHR x Industrial	915	N			
Industrial	915	N			
ENTER LANDFILL	918				

## CHRIN ODOR COMPLAINT LOG (1225 Industrial Dr., Easton, PA 18042)

Date	Time	Address	Distance from Landfill (miles)	Weather Data (Allentown 648E)		Temperature °F	Wind (out of)	Residence / Drive-by	Description / Notes	Gas Management Data				Date of Initial Response	Addressed in Insp Report Dated
				Skies	www.vanderground.com					Flare 1 (scfm)	Flare 3 (scfm)	Flare 4 (scfm)	PPL (scfm)		
01/02/23	17:28	Pine Valley Ter., Easton	NA		53	West 0-1 mph	Drive-by	Calling regarding the Chrin Landfill in Williams Twp. It just stinks so bad on industrial Dr. every time I drive by there. It's dangerous. It's not good to be breathing this or have my kids breathing it, it's just terrible. I don't bother filing out complaints anymore because nothing ever changes. You guys aren't ever going to tell the dump not to be there, you know, no matter what happen until we're supposed to cap it. It definitely smells worse on industrial Dr. than it does at my house. There's not a day that it doesn't stink on industrial Blvd. in the evening and that's when I'm usually driving there. I don't know if it's because once the air cools, something happens.	1672				1672	01/04/23	01/06/23
01/09/23	16:29	Pine Valley Ter., Easton	NA		40	Northwest 0-1 mph	Drive-by	I live in Williams Twp. & I just wanted to let you guys know I smell it now. Today is a colder day. So I can smell it on the switchback coming down to town.	1428				1428	01/26/23	02/09/23
03/31/23	19:33	Pine Valley Ter., Easton	1.348		57	South 5-6 mph	Residence	Odors of human waste have been on caller's property for w few hours.	1540				1540	04/03/23	05/04/23
04/14/23	10:27	Spring Valley Rd., Easton	unknown		79	North 1-2 mph	Residence	Odor complaint-submitted to Williams Twp.	1213				1213	04/17/23	05/04/23
05/06/23	1:46	Merion Ln., Easton	1.744		44	Southeast 0-1 mph	Residence	Heavy gas odor on property	1441				1441	05/08/23	05/04/23
05/07/23	7:43	Merion Ln., Easton	1.744		54	Southeast 0-1mph	Residence	Landfill odor on property	1416				1416	05/08/23	05/04/23
5/7/23?	unknown	Spring Valley Rd., Easton	unknown		no time frame	no time frame	Residence	Odor complaint-submitted to Williams Twp. Odor over the weekend at residence, comes & goes, but no odor at time of call.	1416				1416	05/08/23	05/04/23
06/05/23	6:27	Pine Valley Ter., Easton	1.297				Residence	Smell of rotting fish in garage & car.						06/09/23	06/09/23
07/21/23	0:17	Pine Valley Ter., Easton	1.297				Residence	Landfill associated gaseous smell on my property this morning.						06/09/23	06/09/23
08/18/23	13:05	Waltman Loop Lane	0.943				Residence	I took my dog out at 12:15 AM today and the smell from the landfill made me sick to my stomach, the odor was so strong!						07/24/23	08/01/23
09/12/23	8:05	Pine Valley Ter., Easton	1.297				Residence	Excessive odors from the Chrin landfill. I'm out working in my yard and it's enough to choke a horse!						08/18/23	08/01/23
10/18/23	evening	Spring Valley Rd., Easton	0.818				Residence	Very strong landfill odor detectable on my property the second I walk outside.						09/12/23	09/29/23
10/19/23	1:00	Merion Ln., Easton	1.744				non-residence	calling on behalf of other residents reporting very bad landfill smells on evening of 10/18/23, and all week for the past week, & residents feel that odors are lasting a lot longer than they normally last.						10/19/23	11/16/23
12/02/23	16:33	Merion Ln., Easton	NA				Residence	Odors from Chrin landfill. Smelled like gas. Also recently getting stronger than normal odors when driving by the landfill.						10/19/23	11/16/23
							Drive-by	it smells like gas while driving by the landfill.						12/13/23	12/13/23





2023	Daily	Total Week	Month Average	Day	Total Month	Total Quarter
<b>December</b>						
1	545.0		545.0	1	545.0	25,774.3
2	93.8		319.4	2	638.8	25,868.1
3		<b>2,227.10</b>			638.8	25,868.1
4	610.5		416.4	3	1,249.3	26,478.6
5	527.5		444.2	4	1,776.8	27,006.1
6	496.7		454.7	5	2,273.5	27,502.8
7	509.7		463.9	6	2,783.2	28,012.5
8	510.6		470.5	7	3,293.8	28,523.1
9	65.5		419.9	8	3,359.3	28,588.6
10		<b>2,110.00</b>			3,359.3	28,588.6
11	590.5		438.9	9	3,949.8	29,179.1
12	615.1		456.5	10	4,564.9	29,794.2
13	0.0		415.0	11	4,564.9	29,794.2
14	0.0		380.4	12	4,564.9	29,794.2
15	0.0		351.1	13	4,564.9	29,794.2
16	0.0		326.1	14	4,564.9	29,794.2
17		<b>615.10</b>			4,564.9	29,794.2
18	0.0		304.3	15	4,564.9	29,794.2
19	0.0		285.3	16	4,564.9	29,794.2
20	0.0		268.5	17	4,564.9	29,794.2
21	0.0		253.6	18	4,564.9	29,794.2
22	0.0		240.3	19	4,564.9	29,794.2
23	0.0		228.2	20	4,564.9	29,794.2
24		<b>0.00</b>			4,564.9	29,794.2
25		<b>HOLIDAY</b>			4,564.9	29,794.2
26	0.0		217.4	21	4,564.9	29,794.2
27	0.0		207.5	22	4,564.9	29,794.2
28	0.0		198.5	23	4,564.9	29,794.2
29	0.0		190.2	24	4,564.9	29,794.2
30	0.0		182.6	25	4,564.9	29,794.2
31		<b>0.00</b>			4,564.9	29,794.2
<b>Month Total</b>						
4,564.9						
<b>Quarter Total</b>						
29,794.2						

**Faulch, Amy**

---

**From:** Joe Klobusicky <jklobusicky@chrin.org>  
**Sent:** Tuesday, December 5, 2023 9:59 AM  
**To:** Faulch, Amy; Melody Ernst  
**Cc:** Bellas, Roger; Miller, Rachel; Mullin, Robert  
**Subject:** [External] site update  
**Attachments:** Site Update - december 5th 2023.pdf

**ATTENTION:** This email message is from an external sender. Do not open links or attachments from unknown senders. To report suspicious email, use the [Report Phishing button in Outlook](#).

FYI

We will be doing the following over the next week or so (location photos attached):

**Western end of Landfill - Upper slopes 3D / 3E overfill to bring slope to grade for capping (using excavated old waste to fill) (Started Tuesday, December 5<sup>th</sup>)**

**Eastern end of landfill - Leachate Seep repair area (Work to be started Wednesday, December 6<sup>th</sup>)**

Please let me know if you have any questions.

Sincerely,

Joe Klobusicky  
Chrin Companies

Upper slopes 3D / 3E overfill to bring slope to grade for capping (excavated old waste to fill) (Started Tuesday, December 5<sup>th</sup>)

Leachate Seep repair area (Work to be started Wednesday, December 6<sup>th</sup>)

**Site Update – December 5, 2023 – Chrin Landfill**



Leachate Seep repair area  
(Work to be started Wednesday,  
December 6<sup>th</sup>)

Upper slopes 3D / 3E overfill to  
bring slope to grade for capping  
(excavated old waste to fill)  
(Started Tuesday, December 5<sup>th</sup>)



Upper slopes 3D / 3E overfill to bring slope to grade for capping (excavated old waste to fill) (Started Tuesday, December 5<sup>th</sup>)

West end of landfill



East end of landfill

Leachate Seep repair area (Work to be started Wednesday, December 6<sup>th</sup>)

## Faulch, Amy

---

**From:** Joe Klobusicky <jklobusicky@chrin.org>  
**Sent:** Friday, December 15, 2023 12:13 PM  
**To:** Mullin, Robert  
**Cc:** Faulch, Amy  
**Subject:** [External] FW: November 16 DEP Inspection Follow Up  
**Attachments:** November 2023 DEP Inspection Exceedance Sheet.xlsx

**ATTENTION:** This email message is from an external sender. Do not open links or attachments from unknown senders. To report suspicious email, use the [Report Phishing button in Outlook](#).

FYI – 30 day follow-up

---

**From:** Justin Souders <jsouders@chrin.org>  
**Sent:** Friday, December 15, 2023 10:43 AM  
**To:** Joe Klobusicky <jklobusicky@chrin.org>  
**Subject:** Re: November 16 DEP Inspection Follow Up

Joe,

I got the 30 day follow-ups from this inspection done yesterday. Here is the completed exceedance sheet. No elevated readings were recorded.

Thanks,  
Justin

---

**From:** Justin Souders  
**Sent:** Wednesday, November 29, 2023 8:42 AM  
**To:** Joe Klobusicky <jklobusicky@chrin.org>  
**Subject:** November 16 DEP Inspection Follow Up

Joe,

There were no exceedances recorded when I did the 10-day follow-ups from the DEP Inspection a couple of weeks back. They were completed on November 22. I attached the Exceedance Sheet to this email and will provide an update when the 30-day follow-ups are completed.

Thanks,  
Justin



Electronic File Distribution:

Facility

Williams Township

R. Bellas/R. Miller

AQ: R. Mullin /M. Bardzilouskas

M. Glogowski

R. Malizia

A. Faulch

Chrin: Joseph Klobusicky

[jklobusicky@chrin.org](mailto:jklobusicky@chrin.org)

Williams Township: Melody Ernst

[mernst@williamstwp.org](mailto:mernst@williamstwp.org)