

General Inspection Report

Permit Number	100022	EPA ID Number	----
Facility Name	CHRIN BROS SANI LDFL	Operator Name	CHRIN BROS INC
Address	1225 INDUSTRIAL DR	Address	1225 INDUSTRIAL DR
City/State/Zip	EASTON PA 18042-6829	City/State/Zip	EASTON PA 18042-6829
Municipality	Williams Township	County	Northampton
Responsible Official	Gregory Chrin	Title	Owner/ Operator
Person Interviewed	Joe Klobusicky	Title	Environmental Manager
		Telephone #	1
Lead Inspector	EDWARD MCNULTY	Title	SLD WSTE SPCST
Site ID	238053	Client ID	42952
PF ID	240650	SF ID	201820
Inspection Start Date	07/08/2025 10:05 AM	Inspection End Date	07/08/2025 11:35 AM
Inspection Type	RTPT - Routine/Partial Inspection	Inspection Result	No Violations Noted
Permit Expiration Date	01/06/2030	Days/Week Operated	6
		Max. Daily Volume	2000 Tons/Day

Comments

On July 8, 2025 the PA Department of Environmental Protection ("the Department") conducted a routine partial inspection at Chrin Bros. Sanitary Landfill ("Chrin") in response to an odor complaint received on 7/5/25. Representing the Department was Ed McNulty ("this inspector"). Representing Chrin was Joseph Klobusicky who provided a site tour and was interviewed on behalf of Chrin.

A pre-entry odor patrol was conducted in the vicinity of Chrin. Slight intermittent rotting garbage odors were observed on Cedarville Road, Congressional Road, Clubhouse Road, and on Industrial Drive near Chrin's entrance.

When asked about the source of the odors, Joe Klobusicky said they had been receiving compactors from markets with a lot of rotting food waste from the holiday weekend.

The working face was in stage 7 and had been for the past week. Line odor misters were active at the entrance and along hauling roads. Two portable odor misters were also operating. Water with deodorizer was being sprayed over tipped waste at the working face. Water trucks were running on interior roads for dust control.

Sections had been added to the MSE wall since the last inspection.

Records were not reviewed during this inspection.

This concludes this inspection report.

Inspection Report Signature Page

This inspection report is notice of the findings of an inspection conducted by a representative of the Department. This report is formal notification of any violations observed during the inspection. Additional notification of violations may be issued concerning either Violations noted herein, or other violations identified as a result of review of laboratory analyses. This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein. Signature by the persons interviewed does not necessarily imply concurrence with the findings of this report, but does acknowledge that the person was shown the report or that a copy was left with the person.

Signatures

Person
Interviewed

Unable To Obtain Reason: Delivered via email

Date --/--/----

Inspector



Date 08/08/2025

Investigator: Ed McNulty Date: 7-8-2029 CASE: Chrin
 Weather Conditions: 85°F Sunny, Winds 3mph W, 12% Humidity ODOR PATROL SURVEY

SURVEY LOCATION	TIME	ODOR INTENSITY	ODOR DURATION	ODOR DESCRIPTION	COMMENTS & OBSERVATIONS
		S = Strong M = Moderate SL = Slight N = None	P = Persistent I = Intermittent N = None	EG = Rotten Egg LFG = Landfill Gas G = Garbage S = Sewage D = Dredge O = Other (describe)	
I-78	1005	N	N		
MHR x Industrial	1008	SL	I	G	Slight rotting odor
Cedarville Rd	1009	SL-N	I	G	Garbage odors end around Congressional Rd
Knollwood	1011	N	N		
Auburn	1011	N	N		
Sewage Plant	1015	SL SL	I	O	Smells like a chlorinated swimming pool Before overpass
Congressional	1020	SL-N	I	G	Very faint garbage odors
Clubhouse	1022	N	N		
Turnberry	1024	N	N		
Clubhouse	1026	SL	I	G	Faint garbage between Congr. and Pinchurst
Pinchurst	1027	N	N		
Pine Valley	1029	N	N		
Beth Page	1031				
Waterford	1031				
Old Course	1032				
Oak Hill	1033				
Spring Valley	1036				
Mountain top	1042	↓	↓		

e FACTS # 4011154

